

HISTORIC RESOURCES INVENTORY

NABS _____ NACH _____ LOC _____ SHL NO. _____ INR Status _____
 UTM: A 10/627429/4096097 C _____
 B _____ D _____

IDENTIFICATION

1. Common name: _____
2. Historic name: _____
3. Street or rural address: 7257 Egleberry Street
 City Gilroy Zip 95020 County Santa Clara
4. Parcel number: 79900931
5. Present Owner: Frances Bozzo Address: 780 Eschenberg Dri
 City Gilroy Zip 95020 Ownership is: Public _____ Private X
6. Present Use: Residence Original use: Residence

DESCRIPTION

- 7a. Architectural style: Craftsman Bungalow
- 7b. Briefly describe the present *physical appearance* of the site or structure and describe any major alterations from its original condition:

A single story rectangular structure with a low pitch end gable facade, the exposed eave and brackets together with narrow horizontal board siding are elements of the craftsman style. In this case, a modest style replicated by local contractors in several locations.



8. Construction date:
 Estimated 1920 Factual _____
9. Architect Unknown
10. Builder Unknown
11. Approx. property size (in feet)
 Frontage 51 Depth 140
 or approx. acreage _____
12. Date(s) of enclosed photograph(s)
Mar. 1986

13. Condition: Excellent ___ Good X Fair ___ Deteriorated ___ No longer in existence ___
14. Alterations: _____
15. Surroundings: (Check more than one if necessary) Open land ___ Scattered buildings ___ Densely built-up X
Residential X Industrial ___ Commercial ___ Other: _____
16. Threats to site: None known X Private development ___ Zoning ___ Vandalism ___
Public Works project ___ Other: _____
17. Is the structure: On its original site? X Moved? ___ Unknown? ___
18. Related features: _____

SIGNIFICANCE

19. Briefly state historical and/or architectural importance (include dates, events, and persons associated with the site.)

The varied bungalow styles were readily accepted and adopted into the Gilroy home collection for their many attributes. A pleasant home that featured overhanging eaves providing protection from the summer sun was an important consideration since most were first occupied in the summer months. Recessed porches allowed a place to sit and watch neighborhood activities from a protected vantage point. Ornament and detailing was straight forward reflecting the style of the structure itself. Well suited to the needs of a growing population, the significance to this survey is in the number of homes and variety of styles that remain relatively in their original condition. These create streetscapes that are important because of the unity of the whole more than the special qualities of any individual structure.

20. Main theme of the historic resource: (If more than one is checked, number in order of importance.)
 Architecture 1 Arts & Leisure _____
 Economic/Industrial ___ Exploration/Settlement _____
 Government ___ Military _____
 Religion ___ Social/Education _____

21. Sources (List books, documents, surveys, personal interviews and their dates).
A Field Guide to American Houses
 McAlister
 Sanborn Map 1888, 1908

22. Date form prepared April 1986
 By (name) The Firm of
 Organization BONNIE L. BAMBURG
 Address: 247 N. Third Street
 City San Jose, CA Zip 95112
 Phone: (408) 971-1421

