

HISTORIC RESOURCES INVENTORY

Ser. No. \_\_\_\_\_  
HABS \_\_\_\_\_ HAER \_\_\_\_\_ Loc \_\_\_\_\_ SHL No. \_\_\_\_\_ NR Status 3  
UTM: A 10/ 627072/4097124 C \_\_\_\_\_  
B \_\_\_\_\_ D \_\_\_\_\_

IDENTIFICATION

1. Common name: \_\_\_\_\_
2. Historic name: \_\_\_\_\_
3. Street or rural address: 7832 Eigleberry Street  
City Gilroy Zip 95020 County Santa Clara
4. Parcel number: 79900102
5. Present Owner: Ann Logan Address: 7832 Eigleberry S  
City Gilroy Zip 95020 Ownership is: Public \_\_\_\_\_ Private X
6. Present Use: Residence Original use: Residence

DESCRIPTION

- 7a. Architectural style: Classic Box
- 7b. Briefly describe the present *physical appearance* of the site or structure and describe any major alterations from its original condition:

The classic characteristics of this rare style of house include the hipped roof and the enclosed eaves. There is a lattice windowed dormer on the roof facing the street, wide clapboard siding and a veranda porch supported by thin square columns.



8. Construction date:  
Estimated 1870 Factual \_\_\_\_\_
9. Architect \_\_\_\_\_  
Unknown
10. Builder \_\_\_\_\_  
Unknown
11. Approx. property size (in feet)  
Frontage 47 Depth 138  
or approx. acreage \_\_\_\_\_
12. Date(s) of enclosed photograph(s)  
Mar. 1986

13. Condition: Excellent \_\_\_ Good X Fair \_\_\_ Deteriorated \_\_\_ No longer in existence \_\_\_
14. Alterations: \_\_\_\_\_
15. Surroundings: (Check more than one if necessary) Open land \_\_\_ Scattered buildings \_\_\_ Densely built-up X  
Residential X Industrial \_\_\_ Commercial X Other: \_\_\_\_\_
16. Threats to site: None known X Private development \_\_\_ Zoning \_\_\_ Vandalism \_\_\_  
Public Works project \_\_\_ Other: \_\_\_\_\_
17. Is the structure: On its original site? X Moved? \_\_\_ Unknown? \_\_\_
18. Related features: \_\_\_\_\_

**SIGNIFICANCE**

19. Briefly state historical and/or architectural importance (include dates, events, and persons associated with the site.)

This classic box is an architectural style not popular in Gilroy. Therefore, this is an important and rare example of this style. The very classic window crowns on the sides give a clue that the front has been modified. Not a significant work, this residence fits well with the other older structures in this area.

20. Main theme of the historic resource: (If more than one is checked, number in order of importance.)  
Architecture 1 Arts & Leisure \_\_\_\_\_  
Economic/Industrial \_\_\_ Exploration/Settlement \_\_\_\_\_  
Government \_\_\_ Military \_\_\_\_\_  
Religion \_\_\_ Social/Education \_\_\_\_\_

21. Sources (List books, documents, surveys, personal interviews and their dates).

A Field Guide to American Houses  
McAlister

Sanborn Map 1888,1908

22. Date form prepared April 1986  
By (name) The Firm of  
Organization BONNIE L. BAMBURG  
Address: 247 N. Third Street  
City San Jose, CA Zip 95112  
Phone: (408) 971-1421

Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):

